



压力转换表 Pressure Conversion Table

1Pa=	0,01	mbar
(pascal N/m ²)	1×10 ^(-^7)	bar
	102×10 ^(-^7)	kg/cm ²
	0,102	mm H2O
	0,0075	mm Hg
	145×10 ^(-^6)	psi
1mbar=	100	pa
(millibar)	0,001	bar
	102×10 ^(-^5)	kg/cm ²
	10,2	mm H2O
	0,750	mm Hg
	0,0145	psi
1bar=	100 000	pa
	1000	mbar
	1,02	kg/cm ²
	10 200	mm H2O
	750	mm Hg
	145,038	psi
1Kg/cm ² =	98100	pa
kilogram per cm ²	981	mbar
	0,981	bar
	10 000	mm H2O
	736	psi
	142,233	pa
1mm H2O=	9,81	pa
(mm water gauge)	0,098	mbar
	98,1×10 ^(-^6)	bar
	0,0001	kg/cm ²
	0,0736	mm H2O
	0,001422	psi
1mm Hg=	133,3	pa
(mm mercury)	1,33	mbar
	0,00133	bar
	0,001359	kg/cm ²
	13,59	mm H2O
	0,01934	psi
1psi=	6895,06	pa
(pounds per sq inch)	68,95	mbar
	0,06895	bar
	0,07031	kg/cm ²
	703,01	mm H2O
	51,717	mm Hg

Assembled Shape外形组合:



C: Center (top) 中心, 向上
L: Left 左侧
R: Right 右侧



GPS100系列风压开关订货型号指引

GPS100 Series Air Pressure Switch Ordering Instruction

GPS100	39	90	CC	I	C	Z	G	L
开关类别 Switch Type	关闭压力点 Off Pressure Set Point	开启压力点 On Pressure Set Point	外形组合 Assembled Shape	额定电流 Electrical Rating	端子类型 Terminal Type	接插形式 Circuit Code	微动开关颜色 Color of Micro Switch	压力类型 Pressure Type
GPS100系列风压开关 GPS100 Series Air Pressure Switch	依客户而定 According to customer's requirements	依客户而定 According to customer's requirements	见“外形组合” Refer to "Assembled Shape"	1 <0.1A	C 6.30x0.80mm 0.250"±0.032" 250#快接端子 250#Quick Connect Terminals	C SPST-NC 单极单投-常闭	G 灰色Grey	H 正压 Positive Pressure
				2 >0.1A and <5A	E 4.76x0.5mm 0.187"±0.020" 187#快接端子 187#Quick Connect Terminals	P SPST-NO 单极单投-常开	B 黑色Black	L 负压 Negative Pressure
				3 >5A and <16A		Z SPDT 单极双投		
				4 >16A				